

Flow Meter Battery Pack and Stand



TSI® Model 4199

Operation and Service Manual

P/N 1980504, Revision E
September 2024



This battery pack works with the TSI® Series 4000 and 4100 Flow Meters that have LCD displays. Flow Meters manufactured before August 2004 will not indicate low battery. For those meters, the meter will work properly until the display locks up; replace batteries at that time.

List of Components

1 - Battery pack	2 - 4000 Series lugs
2 - 4100 Series lugs	6 - AA batteries

Installation

Screw in both lugs to back side of flow meter (the front being the display). 4000 and 4100 series flow meters require different size lugs. Line up lugs with the holes on top of the battery pack. Press one lug in at a time. Attach cable to flow meter.

Removal

Unplug power cable and then rotate the bottom of the meter away from the battery pack until lugs disengage from battery pack.



Knowledge Beyond Measure.

TSI Incorporated – Visit our website www.tsi.com for more information.

USA	Tel: +1 800 680 1220	India	Tel: +91 80 67877200
UK	Tel: +44 149 4 459200	China	Tel: +86 10 8219 7688
France	Tel: +33 1 41 19 21 99	Singapore	Tel: +65 6595 6388
Germany	Tel: +49 241 523030		

